





North Elevation



South Elevation



East Elevation

NOTE SCHEDULE	
1	25° CORRUGATE COLOURSTEEL ROOFING
	70 SERIES BRICK VENEER
3	SECTIONAL GARAGE DOOR
4	VERTICAL LINEA OBLIQUE CLADDING
(5)	THERMAL BROKEN DOUBLE GLAZED ALUMINIUM WINDOWS & DOOR

